## **DMV Lane Technician Observation Report**

DMV Technician: Refer Flery - Positio	tion: Lor 2		
Station: New Castre Date: 6-19-13 Time: 12:45			
Vehicle Make: Hondy Model Acciora - Year 2006			
GVWR: Fuel Type: GAS Registration Number: 4061 81			
Auditor: Ogy by/4 Covert Overt (circle one)			
	YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?	6		
2. Was Emissions testing required?	1		
a) Was Emissions testing performed using OBD?	4		
b) Was Emissions testing performed using Analyzer Probe?			
c) Was Emissions testing performed using Paddle(s)?			
d) Was Emissions testing performed using Clip?			
3. Was Catalytic Converter inspection required?			C-
a) Was Catalytic Converter inspection performed?			
4. Was <b>Fuel Tank</b> pressure testing required?			-
a) Was Fuel Tank pressure testing performed?			
5. Was Fuel Cap pressure testing required?			-
a) Was Fuel Cap pressure testing performed?			
6. Is this test a <b>Re-check</b> from a prior failure?			1
a) Which re-check test is being performed? 1 2 3 (circle one)			
b) If this is re-check #3, was repair paperwork verified for waiver?			
New Castle and Kent Counties Only		1. 1	
7. Was Two-Speed Idle testing required?		1	
a) Was Two-Speed Idle testing performed?			
Sussex County Only			
8. Was Curb Idle testing required?			
a) Was Curb Idle testing performed?			
Comment:			
Lane Supervisor Signature:			

Revised 04/12/2013